



From a 2006+ OEM Honda Owners Manual:
 "...Your vehicle displays engine oil life and maintenance service items on the information display to show you when you should have your dealer do engine oil replacement and indicated maintenance service."

SERVICE CODE A - \$39.95 (based on OEM filter & 4.5 qts. oil, add \$10.00 for S2000)

- Replace engine oil, filter and crush washer
- Inspect tires for wear, damage and proper inflation
- Inspect driveshaft boots/bands for wear/damage
- Inspect fluid levels and condition; top off
- Check parking brake adjustment
- Reset Maintenance Minder back to 100%

SERVICE CODE B - \$119.95

- Replace engine oil, oil filter and crush washer
- Rotate tires (except S2000)
- Inspect tires for wear, damage and proper inflation
- Inspect, service/adjust/clean and lubricate front and rear brakes
- Check the parking brake adjustment; adjust as necessary
- Inspect brake lines/hoses/calipers/ABS for leaks/damage
- Inspect tie rod ends, steering gear and boots for leaks/damage
- Inspect suspension components for wear, damage, loose bolts
- Inspect driveshaft boots/bands for wear/damage
- Inspect cooling system for damage/leaks
- Inspect all fluid levels and condition; top off
- Inspect exhaust system/heat shields
- Lubricate hinges, locks and latches
- Test lights and controls for proper operation
- Performance Test 12 Volt Battery
- Reset Maintenance Minder back to 100%

SUB CODE 1 - \$19.95

- Rotate tires (except S2000)
- Inspect tires for wear, damage and proper inflation

SUB CODE 2 - \$169.95 (filter price may vary by model)

- Replace air cleaner element
- Check drive belts for wear, damage and proper tension
- Replace dust and pollen filter
- Align all four wheels

SUB CODE 3 - \$99.95

- Replace transmission fluid
- Flush brake fluid
- Replace Transfer fluid (VTM-4 Only)

SUB CODE 4 - 4 Cylinder - Price varies by model - call for pricing. 262.522.7558 ext.301

- Replace platinum spark plugs
- Inspect valve clearance
- Replace valve cover gasket

SUB CODE 4 - V6 - Price varies by model - call for pricing. 262.522.7558 ext.301

- Replace platinum spark plugs
- Replace timing belt (if equipped)
- Inspect water pump
- Inspect valve clearance (additional)
- Replace water pump (if timing belt is being replaced)
- Inspect timing belt tensioner for leaks (replacement additional)
- Replace valve cover gasket(s) (if cover is removed)
- Replace accessory drive belt(s)
- Replace engine coolant (MM5)

SUB CODE 5 - \$74.99

- Replace engine coolant

SUB CODE 6 - 70W90 \$74.99; Dual Pump \$75.96; VTM-4 \$80.95

- Replace differential fluid (S2000 and AWD models)